

Inspection Report

Report No.: XYBA-141113

Supplier : XY-GLOBAL

Inspection Date: 12th Dec-, 2014

Inspector:LEO

Inspection only for:	<u>Inspection Result:</u>
PO . XYBA-141113 Item No. XY21ZC034	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC034	10000Pcs	7% inspection	0pcs	No failure	10000Pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product:



3. Product:

4. Product:

[illegible]

10 400 10

5. Product :

6. Inspection report:

項目	
材料	指定材料CNC加工指定材料CNC加工
仕様	仕様 AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
公差	公差指定
表面処理	表面処理指定
色	色指定
重量	重量指定
寸法	寸法指定
形状	形状指定
加工	加工指定
検査	検査指定
包装	包装指定
納期	納期指定
価格	価格指定
その他	その他指定
1. 指定材料CNC加工	
2. 指定材料指定	
指定材料AL6061 AL6065AL6063AL7075	
4. 指定材料指定	
5. 公差指定±0.01mm	
6. 重量指定100g	
7. 表面処理指定	
8. 色指定25-30mm	
9. 重量指定指定 指定指定指定	
10. 指定材料指定指定	
11. 指定材料ISO 9001	
指定	
1.10指定ISO	
2. 指定指定指定	
3. 指定指定指定	
4. 指定指定	
5. 指定	
6. 指定	
7. 指定指定指定	
指定	
指定指定指定指定	
指定指定指定	
指定指定ISO9001	
指定指定指定指定	
指定OEM指定	