

Inspection Report

Report No.: XYN-140524
Supplier : XY-GLOBAL

Inspection Date: 19th Jun, 2014
Inspector: Ken

Inspection only for: PO . XYN-140524 Item No.XY-142537	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-142537	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing




2. Product



3. Product



4 Product



5. Product:

6. Report:

品名	高精度超精密加工OEM部品
品番	品番ADC12/A380
単位	個
仕様	高精度超精密加工
材質	アルミニウム
加工	CNC加工
公差	公差gague
表面処理	無
寸法	+/-0.01mm
重量	T / T 50mm50mmT / T
用途	高精度超精密加工
備考	高精度超精密加工
単位	個
重量	T / T 50mm20-25 NBSP
品名	高精度超精密加工
1.Name 高精度超精密加工	
2.Process 高精度超精密加工	
品番ADC12/A380	
4.高精度超精密加工	
5.Tolerance 公差±0.01mm	
6.重量100mm	
7.Specification 品番serice	
8.重量25-30mm	
9.高精度超精密加工accessoried	
10.高精度超精密加工Austrial	
11&NBSP;品番ISO 9001	
品番	
1品10mmISO	
2品	
3品kinds available	
4品	
5品	
6品	
7品	
品番	
品番NBSP;品番	
品番	
品番ISO9001	
品番	
品番OEM	