

## Inspection Report

**Report No.:** XYAN-150305

Supplier : XY-GLOBAL

Inspection Date: 3<sup>th</sup> Apr-, 2015

Inspector:LEO

|                                          |                           |
|------------------------------------------|---------------------------|
| Inspection only for:                     | <u>Inspection Result:</u> |
| PO . XYBA-150305      Item No. XY21ZC092 | PASS                      |

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY21ZC092   | 8000pcs       | 7% inspection | 0pcs         | No failure          | 8000pcs         |

**Appearance Inspection :**

|             |
|-------------|
| No failure. |
|-------------|

**Dimension Inspection:**

No failure , below measurement report for reference.

**Assembly Test:**

|            |
|------------|
| No failure |
|------------|

## Inspection Summary

The inspection sample plan is 100% inspection.

## Digital photo records :



1. Packing

2. Product:



3. Product:

4. Product:

[illegible]

5. Product :

6. Inspection report:

[illegible]

## Safety is our serious job for our worker and engineer team

