

Inspection Report

Report No.: XYI-140302
Supplier : XY-GLOBAL

Inspection Date: 5th Apr, 2014
Inspector: Leo

Inspection only for: PO : XYI-140302 Item No.140110	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
140110	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:



7. Product:

A detailed inspection report table with multiple columns and rows, containing various data points and signatures.

8. Report:

品名	高精度加工品OEM品
品番	ADC12 A380
単位	個
仕様	
材質	ADC12
加工	CNC加工
公差	±0.01mm
表面処理	無処理
検査	全数検査
納期	約2週間
梱包	10個/箱
備考	
1.Name	高精度加工品
2.Process	CNC加工
3.公差	±0.01mm
4.表面処理	無処理
5.Tolerance	±0.01mm
6.単位	100個
7.Specification	serice
8.検査	25-30個
9.付属品	accessoried
10.梱包	Austrial
11&NBSP;	ISO 9001
品番	
1	10個/箱
2	ISO 9001
3	kindls available
4	
5	
6	
7	
品番	
備考	ISO 9001
品番	
品番	OEM品