

5. Product :

XY-6L BAL XY Electronics Technology Co., Ltd Inspection Report

Report No.: XYAN-150320 Inspection Date: 25^{th-} Apr-, 2015 Supplier: XY-GLOBAL Inspector:LEO

Inspection only for: PO . XYBA-150320 Inspection Result: PASS Item No. XY21ZC107

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC107	10000pcs	7% inspection	0pcs	No failure	10000pcs

Appearance Inspection :	
No failure,	
Dimension Inspection:	
No failure , below measurement report for reference.	
Assembly Test:	
No failure	
Inspection Summary	
The inspection sample plan is 100% inspection.	



6. Inspection report:



Safety is our serious job for our worker and engineer team

