

Inspection Report

Report No.: XYCY-150228
Supplier : XY-GLOBAL

Inspection Date: 20th Mar, 2015
Inspector: Leo

Inspection only for: PO . XYCY-150228 Item No. XY31CY003	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY003	40000PCS	1% inspection	0pcs	No failure	40000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing



2. Product



3. Product



4 Product



深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Item	Inspection Result	Inspection Date	Inspection Location
1. Appearance	OK	2015.03.20	XY Electronics Technology Co., Ltd
2. Dimension	OK	2015.03.20	XY Electronics Technology Co., Ltd
3. Assembly	OK	2015.03.20	XY Electronics Technology Co., Ltd
4. Function	OK	2015.03.20	XY Electronics Technology Co., Ltd
5. Reliability	OK	2015.03.20	XY Electronics Technology Co., Ltd
6. Safety	OK	2015.03.20	XY Electronics Technology Co., Ltd
7. Environmental	OK	2015.03.20	XY Electronics Technology Co., Ltd
8. Others	OK	2015.03.20	XY Electronics Technology Co., Ltd

5. Product:

6. report

品名	汎用部品CNC加工品汎用部品CNC加工品
材質	材質 AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
仕様	仕様
数量	数量
単位	単位
公差	公差
表面処理	表面処理
検査	検査
納期	納期
価格	価格
備考	備考
1.汎用部品CNC加工品	
2.汎用部品CNC加工品	
汎用部品AL6061 AL6065AL6063AL7075	
4.汎用部品CNC加工品 仕様	
5.汎用部品±0.01mm	
6.汎用部品100mm	
7.汎用部品CNC加工品	
8.汎用部品25-30mm	
9.汎用部品CNC加工品 汎用部品CNC加工品	
10.汎用部品CNC加工品	
11汎用部品ISO 9001	
汎用部品	
1.10汎用部品ISO加工	
2.汎用部品CNC加工品	
3.汎用部品CNC加工品	
4.汎用部品CNC加工品	
5.汎用部品	
6.汎用部品	
7.汎用部品CNC加工品	
汎用部品	
汎用部品CNC加工品	
汎用部品CNC加工品	
汎用部品ISO9001	
汎用部品CNC加工品	
汎用部品CNC加工品	
汎用OEM加工品	