

Inspection Report

Report No.: XYCY-150308
Supplier : XY-GLOBAL

Inspection Date: 3rd Apr, 2015
Inspector: Leo

Inspection only for: PO : XYCY-150308 Item No. XY31CY010	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY010	18000PCS	1% inspection	0pcs	No failure	18000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. report

品名	汎用部品CNC加工品汎用部品CNC加工品
材質	材質 AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
仕様	汎用仕様
数量	数量1000個数量1000個数量1000個
単位	個
備考	汎用部品汎用部品汎用部品汎用部品汎用部品 汎用
備考	汎用部品汎用部品汎用部品 汎用部品汎用部品汎用部品汎用部品汎用部品汎用部品
備考	汎用部品
公差	+/-0.01mm
備考	長さ50mm長さ50mm長さ50mm
備考	汎用部品汎用部品汎用部品汎用部品汎用部品汎用部品汎用部品
単位	個
単位	個
単位	長さ50mm長さ25mm
備考	汎用部品
1.汎用部品CNC加工	
2.汎用部品汎用部品	
汎用部品AL6061 AL6065AL6063AL7075	
4.汎用部品汎用部品 汎用	
5.公差±0.01mm	
6.長さ100mm	
7.汎用部品汎用部品汎用部品	
8.長さ25-30mm	
9.汎用部品汎用部品 汎用部品汎用部品	
10.汎用部品汎用部品汎用部品	
11汎用部品ISO 9001	
汎用部品	
1.10汎用部品ISO	
2.汎用部品汎用部品	
3.汎用部品汎用部品	
4.汎用部品	
5.汎用部品	
6.汎用部品	
7.汎用部品汎用部品	
汎用部品	
汎用部品汎用部品汎用部品	
汎用部品汎用部品	
汎用部品ISO9001	
汎用部品汎用部品汎用部品	
汎用OEM汎用部品	