

Inspection Report

Report No.: XYKS-140611
Supplier : XY-GLOBAL

Inspection Date: 5th July, 2014
Inspector: Leo

Inspection only for: PO : XYSK-140611 Item No. XY31SY55	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY55	12000PCS	1% inspection	0pcs	No failure	12000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Product Type: XY31SY55 Inspection Date: 2014-07-05
Lot No: 140611-001 Date of Report: 2014-07-05

Inspector: Leo

Inspection Result: PASS

Inspection Method: 100% inspection

Inspection Location: XY Electronics Technology Co., Ltd

Inspection Equipment: Vernier Caliper

Inspection Results:

Item	Specification	Inspection Results	Remarks
1	Material	OK	
2	Dimension	OK	
3	Appearance	OK	
4	Assembly	OK	
5	Test	OK	
6	Storage	OK	
7	Transportation	OK	
8	Usage	OK	
9	Maintenance	OK	
10	Disposal	OK	

Inspector: Leo Date: 2014-07-05

6. report

品名	汎用部品CNC加工品汎用部品CNC加工品
材質	材質 AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
仕様	仕様
数量	数量
単位	単位
公差	公差
表面処理	表面処理
検査	検査
納期	納期
価格	価格
備考	備考
1.汎用部品CNC加工品	
2.汎用部品CNC加工品	
汎用部品AL6061 AL6065AL6063AL7075	
4.汎用部品CNC加工品 仕様	
5.汎用部品±0.01mm	
6.汎用部品100mm	
7.汎用部品CNC加工品	
8.汎用部品25-30mm	
9.汎用部品CNC加工品 汎用部品CNC加工品	
10.汎用部品CNC加工品	
11.汎用部品ISO 9001	
汎用部品	
1.10汎用部品ISO加工	
2.汎用部品CNC加工品	
3.汎用部品CNC加工品	
4.汎用部品CNC加工品	
5.汎用部品	
6.汎用部品	
7.汎用部品CNC加工品	
汎用部品	
汎用部品CNC加工品	
汎用部品CNC加工品	
汎用部品ISO9001	
汎用部品CNC加工品	
汎用部品CNC加工品	
汎用OEM加工品	

Safety is our serious job for our worker and engineer team

