

Inspection Report

Report No.: XYSL-150709

Supplier : XY-GLOBAL

Inspection Date: 12th Aug, 2015

Inspector: Leo

Inspection only for: PO . XYSL-150709 Item No. XY31XL029	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL029	10000PCS	1% inspection	Opes	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

[illegible]

6. report

[illegible]

Safety is our serious job for our worker and engineer team

