

Inspection Report



Report No.: XYF-130804
Supplier : XY-GLOBAL

Inspection Date: 1st Sep, 2013
Inspector: LEO

Inspection only for: PO : XYK-130804 Item No.100-23-870	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
100-23-870	30000Set	100% inspection	0pcs	No failure	30000Set

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. inspection reports

[illegible]