

Inspection Report

Report No.: XYLA-150403

Supplier : XY-GLOBAL

Inspection Date: 7th May, 2015

Inspector: Leo

Inspection only for: PO . XYLA-150403 Item No. XY31PC013	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC013	25000PCS	1% inspection	Opcs	No failure	25000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

	2015-2016	2016-2017	2017-2018	2018-2019	2019-2020
A	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
B	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
C	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
D	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
E	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
F	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
G	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
H	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
I	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
J	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
K	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
L	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
M	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
N	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
O	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
P	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
Q	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
R	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
S	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
T	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
U	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
V	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
W	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
X	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
Y	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00
Z	10,000.00	10,000.00	10,000.00	10,000.00	10,000.00

6. report

[illegible]

High qualified surface treatment can make your parts perfect !!!

