

Inspection Report

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for:	<u>Inspection Result:</u>
PO . XYSK-140608 Item No. XY31SY008	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY008	15000PCS	1% inspection	0pcs	No failure	15000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. report

11

品名	CNC加工品CNC加工品
材質	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
仕様	
数量	
単位	
備考	
納入期	
価格	
納期	
品質	
保証	
梱包	
出荷	
検出	
検査	
不良	
返品	
廃棄	
その他	

1. 1. CNC

2.

AL6061 AL6065 AL6063 AL7075

[illegible]

5.□□□□□□±0.01□□

6. 100

7.

8. 25-30

9. □□□□□□□□□□□□□□ □□□□□□□□□□□□

10.

11 □ □ □ □ □ □ □ □ ISO 9001

--	--	--	--	--

1.10 □□□□□ISO□□

2.

3.

4. □□□□□□□□

5.□□□□□

6. □□□□□□

7.□□□□□□□□□□□□□□

□□□□□

[illegible]

□□□□□□□□ISO9001

[illegible]

□□OEM□□□□□□