

Inspection Report

Report No.: XYBA-140922

Inspection Date: 18th Oct., 2014


Supplier : XY-GLOBAL

Inspector: LEO

Inspection only for:	Inspection Result:
PO : XYBA-140922 Item No. XY21ZC015	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC015	1200Set	7% inspection	0pcs	No failure	2000Set

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

11

品名	铝合金CNC加工件CNC件
材料	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
规格	定制
数量	1000个
单位	个
重量	约1.5kg
尺寸	长100mm 宽50mm 高25mm
公差	+/-0.01mm
表面处理	阳极氧化
包装	泡沫箱+气泡膜
交货期	15天
备注	请提供详细图纸

1. 1. CNC

2.

AL6061 AL6065 AL6063 AL7075

4. □□□□□□□□□□□□□□□□ □□□□

5.□□□□□□±0.01□□

6. 100

7.

8. 25-30

9. □□□□□□□□□□□□□□ □□□□□□□□□□□□

10.

11□□□□□□□□ISO 9001

--	--	--	--	--

1.10 1000000 ISO

2.

3. □□□□□□□□□□□□□□

4. □□□□□□□□

5.□□□□□

6.□□□□□□

7.

--	--	--	--	--

[illegible][illegible]

□□□□□□□□□□ISO9001

[illegible]

☐ OEM	☐	☐	☐	☐	☐
------------------------------	--------------------------	--------------------------	--------------------------	--------------------------	--------------------------