

Inspection Report

Report No.: XYBA-141120

Inspection Date: 19th Dec., 2014

Supplier : XY-GLOBAL

Inspector:LEO

Inspection only for: PO . XYBA-141120 Item No. XY21ZC039	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC039	5000Pcs	7% inspection	0pcs	No failure	6000Pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing



2. Product:



3. Product:



4. Product:



5. Product :

6. Inspection report:

11

品名	铝合金CNC加工件CNC件
材料	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
规格	定制
数量	1000个
单位	个
重量	约1.5kg
尺寸	长100mm 宽50mm 高25mm
公差	+/-0.01mm
表面处理	阳极氧化
包装	泡沫箱+气泡膜
交货期	15天
备注	请提供详细图纸

1. 1. CNC

2.

AL6061 AL6065 AL6063 AL7075

4. □□□□□□□□□□□□□□□□ □□□□

5.□□□□□□±0.01□□

6. 100

7.

8. 25-30

9. □□□□□□□□□□□□□□ □□□□□□□□□□□□

10.

11 □ □ □ □ □ □ □ □ ISO 9001

--	--	--	--	--

1.10 □□□□□ISO□□

2.

3. □□□□□□□□□□□□□□

[illegible]

5.□□□□□

6.□□□□□□

7.

--	--	--	--	--

[illegible]

□ □ □ □ □ □ □ □ ISO9001

[illegible]

OEM					
-----	--	--	--	--	--