

Inspection Report

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO . XYLA-150412 Item No. XY31PC022	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC022	25000PCS	1% inspection	Opcs	No failure	25000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

[illegible]

6. report

品名	CNC加工部品CNC部
材質	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
仕様	
数量	
単位	
納入期	
納期	
備考	
図面	
検査	
保管	
梱包	
公差	+/-0.01mm
寸法	最大50mm最小50mm
表面処理	
色	
重量	
価格	最大50円未満25円以上
送料	
1.CNC加工部品CNC部	
2.	
AL6061 AL6065AL6063AL7075	
4.	
5. $\pm 0.01\text{mm}$	
6.100mm	
7.	
8.25-30mm	
9.	
10.	
11.ISO 9001	
1.10ISO	
2.	
3.	
4.	
5.	
6.	
7.	
ISO9001	
OEM	

High qualified surface treatment can make your parts perfect !!!

