

Inspection Report

Report No.: XYBA-141111

Supplier : XY-GLOBAL

Inspection Date: 12th Dec-, 2014

Inspector:LEO

Inspection only for: PO . XYBA-141111 Item No. XY21ZC028	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC028	6000Pcs	7% inspection	0pcs	No failure	6000Pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product:	
-------------	--



3. Product:	
-------------	--

4. Product:	
-------------	--

[illegible]

5. Product :

6. Inspection report:

11

品名	铝合金CNC加工件CNC件
材料	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
规格	定制
数量	10000件
单位	件
重量	约100kg
尺寸	长100mm 宽50mm 高20mm
表面处理	阳极氧化 喷砂 电泳 电镀
包装	泡沫箱+气泡膜+木架
交货期	15天
公差	±0.01mm
最小起订量	50件
付款方式	预付30% 货到付70%
交货地点	工厂
联系人	王经理
电话	13800000000
地址	深圳市宝安区

1. 1. CNC

2.

AL6061 AL6065 AL6063 AL7075

4. □□□□□□□□□□□□□□□□ □□□□

5.□□□□□□±0.01□□

6. 100

7.

8. 25-30

9. □□□□□□□□□□□□□□□□ □□□□□□□□□□□□□□

10.

11□□□□□□□□ISO 9001

--	--	--	--	--

1.10 10000 ISO 100

2.

3. □□□□□□□□□□□□□□

[illegible]

5.□□□□□

6.□□□□□□

7.

--	--	--	--	--

[illegible]

□□□□□□□□□□ISO9001

[illegible]

OEM
