

## Inspection Report


Report No.: XYSL-150608  
Supplier : XY-GLOBAL

Inspection Date: 10<sup>th</sup> July, 2015  
Inspector: Leo

|                                                             |                            |
|-------------------------------------------------------------|----------------------------|
| Inspection only for:<br>PO : XYSL-150608 Item No. XY31XL006 | Inspection Result:<br>PASS |
|-------------------------------------------------------------|----------------------------|

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY31XL006   | 16000PCS      | 1% inspection | 0pcs         | No failure          | 16000pcs        |

|                                                      |
|------------------------------------------------------|
| <b>Appearance Inspection :</b>                       |
| No failure,                                          |
| <b>Dimension Inspection:</b>                         |
| No failure , below measurement report for reference. |
| <b>Assembly Test:</b>                                |
| No failure                                           |
| <b>Inspection Summary</b>                            |
| The inspection sample plan is 100% inspection.       |

|                                                                                     |                                                                                     |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Digital photo records :                                                             |                                                                                     |
|   |  |
| 1. Packing                                                                          | 2. Product                                                                          |
|  |  |
| 3. Product                                                                          | 4 Product                                                                           |
|  |  |
| 5. Product:                                                                         | 6. report                                                                           |



Safety is our serious job for our worker and engineer team

