

Inspection Report

Report No.: XYN-140606
Supplier : XY-GLOBAL

Inspection Date: 1th July, 2014
Inspector: Leo

Inspection only for: PO : XYN-140606 Item No.103546	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
103546	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product




5. Product:



6. Product::



5. Product:



6. Report:

	CNC CNC CNC
	AL6061 AL6065AL6063AL7075&NBSP; SUS304SUS303SUS316
	CNC
	gague
	+/-0.01
	T / T 50T / T
	T / T 5020-25 NBSP
1.Name cnc	
2.Process	
AL6061 AL6065AL6063AL7075	
4.	
5.Tolerance±0.01	
6.100	
7.Specificationserice	
8.25-30	
9.accessoried	
10.Austrial	
11&NBSP;ISO 9001	
110ISO	
2	
3kindlsavailable	
4	
5	
6	
7	
&NBSP;	
ISO9001	