

Inspection Report

Report No.: XYBA-140927

Supplier : XY-GLOBAL


Inspection Date: 27th Oct., 2014

Inspector: LEO

Inspection only for:	Inspection Result:
PO : XYBA-140927 Item No. XY21ZC019	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC019	3800pcs	7% inspection	0pcs	No failure	3800pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

項目	
項目名	高精度CNC加工品CNC加工品
材質	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
形状	任意形状
公差	標準公差/高精度加工品
表面	標準表面/鏡面仕上げ
加工	切削加工/研磨加工/電解研磨
検査	寸法検査/表面検査/硬度検査
単位	mm
公差	+/-0.01mm
加工	最小加工50mm/最大加工500mm
加工	最小加工径φ5mm/最大加工径φ500mm
加工	最小加工深1mm/最大加工深100mm
加工	最小加工厚1mm/最大加工厚100mm
加工	最小加工径φ5mm/最大加工径φ25mm
加工	最小加工厚1mm/最大加工厚100mm
1.高精度CNC加工品	
2.高精度加工品	
項目名AL6061 AL6065AL6063AL7075	
4.高精度加工品	
5.公差±0.01mm	
6.最小加工100mm	
7.最小加工径φ5mm/最大加工径φ500mm	
8.最小加工25-30mm	
9.高精度加工品	
10.高精度加工品	
11.高精度加工品ISO 9001	
項目名	
1.10高精度ISO加工品	
2.高精度加工品	
3.高精度加工品	
4.高精度加工品	
5.高精度加工品	
6.高精度加工品	
7.高精度加工品	
項目名	
高精度加工品	
高精度加工品	
高精度加工品ISO9001	
高精度加工品	
OEM加工品	