

Inspection Report

Report No.: XYDS-140618

Inspection Date: 15th July, 2014

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO . XYDS-140618 Item No.801-30-210	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
801-30-210	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

			
1. Packing		2. Product	
			
3. Product		4 Product	
			
5. Product:		6. Product	

品名	CNC加工品CNC加工品
材質	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
仕様	標準仕様
数量	数量指定可（最小ロット単位）
納期	標準納期あり
梱包	標準梱包あり
検査	全工程検査あり（必要に応じて追加検査も可能）
保証	品質保証あり（不良品交換・返金対応）
送料	別途見積り
公差	+/-0.01mm
重量	重量約50kg（製品仕様により変動）
用途	機械部品、構造材など幅広い用途に利用可能
特徴	高精度加工、強度向上、表面処理オプションあり
備考	
お問い合わせ先	営業部 03-XXXX-XXXX
会社概要	
1. 当社は CNC 加工の専門メーカーとして、お客様のニーズに応じた精密加工を提供しています。	
2. 主要な加工材料は以下の通りです。	
加工材料：AL6061 AL6065AL6063AL7075	
4. 加工精度は ±0.01mm と高精度を実現しています。	
5. 公差範囲は ±0.01mm です。	
6. 加工サイズは最大 100mm です。	
7. 加工形状は平面、曲面、穴加工など多岐にわたります。	
8. 加工リードタイムは 25-30 日程度です。	
9. 表面処理は阳极酸化、黒染めなどに対応しています。	
10. ISO 9001 認証を取得し、品質管理を徹底しています。	
11. ISO 9001 認証番号は XXXX-YYYY-ZZZZ です。	
お問い合わせ先	
1.10 営業部 ISO 課	
2. 技術部 設計課	
3. 生産部 製造課	
4. 品質管理部	
5. 物流課	
6. 経理課	
7. 総務課	
お問い合わせ先	
〒100-0001 東京都千代田区千代田 1-1-1	
TEL: 03-XXXX-XXXX FAX: 03-XXXX-XXXX	
Eメール: info@xxxx.co.jp	
ISO9001 認証番号: XXXX-YYYY-ZZZZ	
OEM 加工も承ります。	