

## Inspection Report

Report No.: XYAN-150418

Supplier : XY-GLOBAL


Inspection Date: 22<sup>nd</sup> May-, 2015

Inspector: LEO

|                                          |                    |
|------------------------------------------|--------------------|
| Inspection only for:                     | Inspection Result: |
| PO . XYAN-150418      Item No. XY21ZC084 | PASS               |

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY21ZC084   | 12000pcs      | 7% inspection | 0pcs         | No failure          | 12000pcs        |

|                                                      |
|------------------------------------------------------|
| <b>Appearance Inspection :</b>                       |
| No failure,                                          |
| <b>Dimension Inspection:</b>                         |
| No failure , below measurement report for reference. |
| <b>Assembly Test:</b>                                |
| No failure                                           |
| <b>Inspection Summary</b>                            |
| The inspection sample plan is 100% inspection.       |

|                                                                                     |                                                                                     |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Digital photo records :                                                             |                                                                                     |
|   |   |
| 1. Packing                                                                          | 2. Product:                                                                         |
|  |  |
| 3. Product:                                                                         | 4. Product:                                                                         |
|  |  |
| 5. Product :                                                                        | 6. Inspection report:                                                               |

[illegible]

## Safety is our serious job for our worker and engineer team

