

Inspection Report

Supplier : XY-GLOBAL

Inspector: Leo

Inspector: Leo

Inspection only for: PO . XYSL-130513 Item No. XY11SL007	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL007	6000PCS	5% inspection	0pcs	No failure	5000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure, below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

[illegible]

6. The test report

