

Inspection Report

Report No.: XYSK-140623

Supplier : XY-GLOBAL

Inspection Date: 15th July, 2014

Inspector: Leo

Inspection only for:	Inspection Result:
PO : XYSK-140623 Item No. XY31SY020	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY020	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Report

Product Name: XY31SY020
Product Type: XY31SY020
Inspection Date: 2014.07.15
Inspector: Leo

Inspection Item: XY31SY020
Inspection Method: 100% inspection
Inspection Result: PASS

Inspection Details:

Item	Requirement	Actual	Result
1. Appearance	1.1. No visible defects	1.1. No visible defects	Pass
2. Dimensions	2.1. Dimensions within tolerance	2.1. Dimensions within tolerance	Pass
3. Functionality	3.1. Functionality within tolerance	3.1. Functionality within tolerance	Pass
4. Assembly	4.1. Assembly within tolerance	4.1. Assembly within tolerance	Pass
5. Packaging	5.1. Packaging within tolerance	5.1. Packaging within tolerance	Pass

Inspection Summary: All items passed inspection.

Inspector: Leo

5. Product:

6. report

11

品名	CNC加工品CNC加工品
材質	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
仕様	標準仕様
数量	100個
単位	個
備考	※本製品は、精密加工品であり、寸法公差は厳格に管理されています。
納入期	約1週間
価格/個	+/-0.01mm
重量	約50g（目安）
梱包	ダンボール箱入り（10個入）
保証	品質保証あり
納期	約50日～25日
その他	お問い合わせください

1. 1. CNC

2.

AL6061 AL6065 AL6063 AL7075

4. □□□□□□□□□□□□□□□□ □□□□

5.□□□□□□±0.01□□

6. 100 [illegible]

8. 25-30

9. □□□□□□□□□□□□□□ □□□□□□□□□□□□

10.

11□□□□□□□□ISO 9001

--	--	--	--	--

1.10 ISO

2.

3. □□□□□□□□□□□□□□

4. □□□□□□□□

5.□□□□□

6.□□□□□□

7.

--	--	--	--	--

[illegible][illegible]

□□□□□□□□□□ISO9001

[illegible]

OEM
