

Inspection Report

Report No.: XYD-140517
Supplier : XY-GLOBAL

Inspection Date: 14th Jun, 2014
Inspector: Ken

Inspection only for: PO . XYD-140517 Item No.XY-144201	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-144201	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

A screenshot of a detailed inspection report table. It contains multiple columns for various inspection parameters and rows of data. The table is titled 'pocdmis' in the top left corner.

6. Report:

[illegible]