

Inspection Report

Report No.: XYSK-140605

Supplier : XY-GLOBAL

Inspection Date: 2th July, 2014

Inspector: Leo

Inspection only for:	<u>Inspection Result:</u>
PO . XYSK-140605 Item No. XY31SY005	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY005	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product

[illegible]

5. Product:

6. report

11

[illegible]

1. 1. CNC

2.

AL6061 AL6065 AL6063 AL7075

4. □□□□□□□□□□□□□□□□ □□□□

5.□□□□□□±0.01□□

6. 100

7.

8. 25-30

9. □□□□□□□□□□□□□□□□ □□□□□□□□□□□□□□

10.

11□□□□□□□□ISO 9001

--	--	--	--	--

1.10 1000000 ISO 100

2. □□□□□□□□□□□□

3.

4.

5. □□□□□

6.□□□□□□

7. □□□□□□□□□□□□□□□□

[illegible][illegible]

□□□□□□□□□□ISO9001

[illegible]

OEM
