

Inspection Report


Report No.: XYN-140521
Supplier : XY-GLOBAL

Inspection Date: 16th Jun, 2014
Inspector: Ken

Inspection only for: PO . XYN-140521 Item No.XY-142037	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-142037	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

	OEM
ADC12A380	
	CNC
	gague
+/-0.01	
T / T 50T / T	
T / T 5020-25 NBSP	
1.Name	
2.Process	
ADC12A380	
4.	
5.Tolerance±0.01	
6.100	
7.Specificationserice	
8.25-30	
9.accessoried	
10.Austrial	
11&NBSP;ISO 9001	
110ISO	
2	
3kindlsavailable	
4	
5	
6	
7	
NBSP;	
ISO9001	
OEM	