

Inspection Report

Report No.: XYDA-150311

Supplier : XY-GLOBAL

Inspection Date: 4th Apr, 2015

Inspector: Leo

Inspection only for:	Inspection Result:
PO : XYDA-150311 Item No. XY31CY029	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY029	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Product Name	XYDA-150311	Product Type	XYDA-150311	Inspection Date	2015.04.04
Order No.	XYDA-150311	Lot No.	XYDA-150311	Inspection Time	14:00:00
Inspector	Leo	Inspector	Leo	Inspector	Leo

Inspection Result: **PASS**

Inspection Summary: The inspection sample plan is 100% inspection.

Inspection Details:

Item	Check Item	Check Result	Check Method	Check Date	Check Time
1	Appearance	OK	Visual	2015.04.04	14:00:00
2	Dimension	OK	Caliper	2015.04.04	14:00:00
3	Assembly	OK	Assembly	2015.04.04	14:00:00
4	Function	OK	Function	2015.04.04	14:00:00
5	Material	OK	Material	2015.04.04	14:00:00
6	Label	OK	Label	2015.04.04	14:00:00
7	Storage	OK	Storage	2015.04.04	14:00:00
8	Transportation	OK	Transportation	2015.04.04	14:00:00
9	Usage	OK	Usage	2015.04.04	14:00:00
10	Maintenance	OK	Maintenance	2015.04.04	14:00:00
11	Disposal	OK	Disposal	2015.04.04	14:00:00
12	Recycling	OK	Recycling	2015.04.04	14:00:00
13	Other	OK	Other	2015.04.04	14:00:00

Inspector: Leo

Inspector Signature: _____

Inspector Date: 2015.04.04

5. Product:

6. report

[illegible]