

Inspection Report

Report No.: XYSK-140621

Supplier : XY-GLOBAL

Inspection Date: 15th July, 2014

Inspector: Leo

Inspection only for:	<u>Inspection Result:</u>
PO . XYSK-140621 Item No. XY31SY019	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY019	10000PCS	1% inspection	Opcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. report

11

品名	CNC加工品CNC加工品
材質	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
仕様	
数量	
単位	
備考	
寸法	+/-0.01mm
重量	約50g
価格	約500円
納期	約2週間
梱包	約50cm x 25cm
その他	

1. 1. CNC

2.

AL6061 AL6065 AL6063 AL7075

4. □□□□□□□□□□□□□□□□ □□□□

5.□□□□□□±0.01□□

6. 100 [illegible]

8. 25-30

9. □□□□□□□□□□□□□□ □□□□□□□□□□□□

10.

11 □ □ □ □ □ □ □ □ ISO 9001

--	--	--	--	--

1.10 □□□□□ISO□□

2.

3.

4. □□□□□□□□

5.□□□□□

6.□□□□□□

7.□□□□□□□□□□

--	--	--	--	--

[illegible][illegible]

□□□□□□□□□□ISO9001

□ □ □ □ □ □ □ □ □ □ □ □ □ □ □

OEM
