

Inspection Report

Report No.: XYI-140320
Supplier : XY-GLOBAL

Inspection Date: 17th Apr, 2014
Inspector: Leo

Inspection only for: PO : XYI-140320 Item No.142089	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
142089	40000PCS	1% inspection	0pcs	No failure	40000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing




2. Product




3. Product




4 Product



5. Product:



6. Product:



7. Product:

8. Report:

品名	ステンレス鋼製精密加工品OEM品
品番	ADC12 A380
材質	ステンレス鋼
仕様	精密加工品
加工方法	CNC加工
公差	±0.01mm
表面処理	研磨
検査方法	目視検査
納入期	約20-25日
梱包	ダンボール箱
1.Name	品名
2.Process	加工方法
3.材料	ADC12 A380
4.公差	±0.01mm
5.Tolerance	±0.01mm
6.表面処理	研磨
7.Specification	仕様書
8.納入期	約25-30日
9.付属品	accessories
10.検査方法	Austrial
11.&NBSP;	ISO 9001
品名	
1.品名	ISO
2.品番	
3.品名	kindls
4.品名	available
5.品名	
6.品名	
7.品名	
品名	
品名	ISO9001
品名	
品名	OEM