

Inspection Report

Report No.: XYDA-140509

Inspection Date: 8th Jun, 2014

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO . XYDA-140509 Item No.1430132	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1430132	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:

