

Inspection Report

Report No.: XYK-130821
Supplier : XY-GLOBAL

Inspection Date: 11th Sep-, 2013
Inspector: Alex

Inspection only for: PO . XYK-130821	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
130014	1000PCS	3% inspection	0pcs	No failure	5000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing

2. Product:



3. Product:

4. Product:



5. Product :

6. Product:

[illegible]