

Inspection Report

Report No.: 140609-V2
Supplier : XY-GLOBAL

Inspection Date: 9th Jun- 2014
Inspector: Leo

Inspection only for: PO . XYS-140519 Item No. Gadget part-2	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
Gadget part-2	1000	1% inspection	0pcs	No failure	1000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product



6. Product

品名	鋼板 CNC加工品CNC加工品
材質	AL6061 AL6065AL6063AL7075&NBSP; SUS304SUS303SUS316
厚さ	1mm
寸法	1000mm x 1000mm
表面処理	研磨仕上げ
公差	CNC加工品±0.01mm
検査方法	目視検査gague検査等
梱包単位	1箱
公差	+/-0.01mm
仕様	T / T 50T / T 50
備考	※ご注文の際は、必ず下記の内容をご確認ください。
品質保証	品質保証書発行可能
納期	約1週間
送料	T / T 5020-25 NBSP
お問い合わせ先	お問い合わせ先
1.Name CNC加工品	
2.Process 切削加工	
3.Material AL6061 AL6065AL6063AL7075	
4.寸法 1000mm x 1000mm	
5.Tolerance ±0.01mm	
6.重量 100kg	
7.Specification serice	
8.温度 25-30℃	
9.付属品 accessoried	
10.認証 Austria	
11.&NBSP; ISO 9001	
お問い合わせ先	
1. 10mm ISO	
2. 10mm	
3. kinds available	
4. 10mm	
5. 10mm	
6. 10mm	
7. 10mm	
お問い合わせ先	
&NBSP;	
ISO9001	