

Inspection Report

Report No.: XYBA-140914

Supplier : XY-GLOBAL


Inspection Date: 3th Oct., 2014

Inspector: LEO

Inspection only for:	Inspection Result:
PO . XYBA-140914 Item No. XY21ZC009	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC009	1200PCS	7% inspection	0pcs	No failure	1200pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

11

品名	铝合金CNC加工件CNC件
材料	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
规格	定制
数量	10000件
单位	件
重量	约100kg
尺寸	长100mm 宽50mm 高20mm
表面处理	阳极氧化 喷砂 电泳 电镀
交货期	10-15天
包装	纸箱
备注	+/-0.01mm
公差	±0.05mm 垂直度0.05mm 平行度0.05mm
检验	首件检验 批量检验
材料	铝合金
重量	约50kg 约25kg
包装	纸箱

1. 1111111111CNC

2.

AL6061 AL6065 AL6063 AL7075

4. □□□□□□□□□□□□□□□□ □□□□

5.□□□□□□±0.01□□

6. 100

7.

8. 25-30

9. □□□□□□□□□□□□□□ □□□□□□□□□□□□

10.

11□□□□□□□□ISO 9001

--	--	--	--	--

1.10 ISO

2.

3. □□□□□□□□□□□□□□

[illegible]

5.□□□□□

6.□□□□□□

7.

--	--	--	--	--

[illegible]

--

□□□□□□□□□□ISO9001

[illegible]

OEM					
-----	--	--	--	--	--