

Inspection Report

Report No.: XYKB-140515

Inspection Date: 11th Jun, 2014

Supplier: XY-GLOBAL

Inspector: Leo

Inspection only for:	Inspection Result:
PO: XYKB-140515 Item No. XY72YM011	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM011	3000PCS	1% inspection	0pcs	No failure	3000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure, below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Item	Inspection Method	Inspection Result	Inspection Date	Inspector
1. Appearance	Visual Inspection	OK	2014.06.11	Leo
2. Dimension	Caliper	OK	2014.06.11	Leo
3. Assembly	Hand Assembly	OK	2014.06.11	Leo
4. Function	Electrical Test	OK	2014.06.11	Leo
5. Reliability	Life Test	OK	2014.06.11	Leo
6. Packaging	Visual Inspection	OK	2014.06.11	Leo
7. Labeling	Visual Inspection	OK	2014.06.11	Leo
8. Storage	Visual Inspection	OK	2014.06.11	Leo
9. Transportation	Visual Inspection	OK	2014.06.11	Leo
10. Disposal	Visual Inspection	OK	2014.06.11	Leo

5. Product:

6. Dimensions report:

