

Inspection Report

Report No.: XYI-140307
Supplier : XY-GLOBAL

Inspection Date: 5th Apr, 2014
Inspector: Leo

Inspection only for: PO : XYI-140307 Item No.140207	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
140207	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure


Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:



7. Product:

8. Report:

	OEM
ADC12A380	
	CNC
	gague
	+/-0.01
	T / T 50T / T
	T / T 5020-25 NBSP
1.Name	
2.Process	
ADC12A380	
4.	
5.Tolerance±0.01	
6.100	
7.Specificationserice	
8.25-30	
9.accessoried	
10.Austrial	
11&NBSP;ISO 9001	
110ISO	
2	
3kindlsavailable	
4	
5	
6	
7	
NBSP;	
ISO9001	
OEM	