

□□□□□□□□



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYK-130819

Inspection Date: 25th Sep-, 2013

Supplier : XY-GLOBAL

Inspector: LEO

Inspection only for:	<u>Inspection Result:</u>
PO : XYK-130819 Item No. 1330025	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1330025	50PCS	100% inspection	0pcs	No failure	50pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure


Inspection Summary

The inspection sample plan is 100% inspection.


Digital photo records :




1. Packing




2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

品名	CNC加工 各種機械部品加工 各種機械部品加工CNC加工CNC 各種機械部品加工 各種機械部品加工
材質	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316各種
形状	各種形状
寸法	各種寸法
公差	±0.01mm
表面処理	各種表面処理
検査	各種検査
納期	各種納期
価格	各種価格
お問い合わせ	各種お問い合わせ
1.Name	各種cnc加工
2.Process	各種加工
3.材質	AL6061 AL6065AL6063AL7075各種
4.形状	各種形状
5.Tolerance	±0.01mm
6.表面処理	各種表面処理
7.Specification	各種serice各種
8.検査	各種検査
9.納期	各種納期
10.価格	各種価格
11&NBSP;	各種ISO 9001
お問い合わせ	各種お問い合わせ
1.10	各種ISO
2.形状	各種形状
3.kindls	available
4.表面処理	各種表面処理
5.検査	各種検査
6.納期	各種納期
7.価格	各種価格
お問い合わせ	各種お問い合わせ
11&NBSP;	各種ISO 9001
お問い合わせ	各種お問い合わせ
1.10	各種ISO
2.形状	各種形状
3.kindls	available
4.表面処理	各種表面処理
5.検査	各種検査
6.納期	各種納期
7.価格	各種価格
お問い合わせ	各種お問い合わせ