

Inspection Report

Report No.: XYSK-140610
Supplier: XY-GLOBAL

Inspection Date: 2th July, 2014
Inspector: Leo

Inspection only for: PO . XYSK-140610 Item No. XY31SY010	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY010	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing



2. Product



3. Product



4. Product



5. Product:

6. report

11

品名	CNC加工品CNC加工品
材質	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
仕様	
数量	
単位	
備考	
納入期	
価格	
納期	
品質	
保証	
梱包	
出荷	
検出	
検査	
不良	
返品	
廃棄	
その他	

1. 1. CNC

2.

AL6061 AL6065 AL6063 AL7075

4. □□□□□□□□□□□□□□□□ □□□□

5.□□□□□□±0.01□□

6. 100

7.

8. 25-30

9. □□□□□□□□□□□□□□ □□□□□□□□□□□□

10.

11 □ □ □ □ □ □ □ □ ISO 9001

--	--	--	--	--

1.10 1000000 ISO

2.

3. □□□□□□□□□□□□□□

4. □□□□□□□□

5.□□□□□

6. □□□□□□

7.□□□□□□□□□□□□□□

□□□□□

[illegible][illegible]

□□□□□□□□ISO9001

[illegible]

□□OEM□□□□□□