

Inspection Report

Report No.: XYDK-130819

Supplier : XY-GLOBAL

Inspection Date:15th Sep-, 2013

Inspector:LEO

Inspection only for:	Inspection Result:
PO . XYDK-130819 Item No.400379	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400379	500PCS	100% inspection	0pcs	No failure	500pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

			
1. Packing		2. Product:	
			
3. Product:		4. Product:	
			
5. Product :		6. Product:	

