

Inspection Report

Report No.: XYSL-130525
Supplier : XY-GLOBAL

Inspection Date: 27th Jun, 2013
Inspector: Leo

Inspection only for: PO : XYSL-130525 Item No. XY11SL015	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL015	10000PCS	5% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.


Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing 	2. Product 
3. Product 	4 Product 
5. Product:	6. The test report

11

[illegible]

1. 1000 000000000000
2. 0000 00000000000000000000
3. 00000000ADC12A3800
4. 00000000000000000000 0000
5. 00000000 ± 0.01 00
6. 00000000100000
7. 000000000000000000000000
8. 0000000025-3000
9. 00000000000000000000 0000000000000000
10. 00000000000000000000
11. 0000000000ISO 9001

00000

- 1.10 國際標準化組織
2. 國際標準化組織
3. 國際標準化組織
4. 國際標準化組織
5. 國際標準化組織
6. 國際標準化組織
7. 國際標準化組織

1111

[illegible][illegible]

ISO9001

[illegible]

OEM
