

Inspection Report

Report No.: XYKS-140614
Supplier : XY-GLOBAL

Inspection Date: 10th July, 2014
Inspector: Leo

Inspection only for: PO : XYSK-140614 Item No. XY31SY57	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY57	12000PCS	1% inspection	0pcs	No failure	12000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Report

Product Name	XY31SY57	Inspection Date	2014-07-10
Product Type	XY31SY57	Inspector	Leo
Product Qty	12000PCS	Inspection Qty	12000PCS
Product Description	XY31SY57		

Inspection Result: PASS

Inspection Summary: The inspection sample plan is 100% inspection.

Inspector: Leo

6. report

[illegible]

Safety is our serious job for our worker and engineer team

