

Inspection Report


Report No.: XYN-140602
Supplier : XY-GLOBAL

Inspection Date: 1st July, 2014
Inspector: Leo

Inspection only for: PO . XYN-140602 Item No.201978	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
201978	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

	CNC
	AL6061 AL6065AL6063AL7075&NBSP; SUS304SUS303SUS316
	&NBSP;
	CNC
	gague
	+/-0.01
	T / T 50T / T
	T / T 5020-25 NBSP
1.Name cnc	
2.Process	
AL6061 AL6065AL6063AL7075	
4.	
5.Tolerance±0.01	
6.100	
7.Specificationserice	
8.25-30	
9CNCaccessoried	
10Austrial	
11&NBSP;ISO 9001	
110ISO	
2	
3kindlsabailable	
4	
5	
6	
7	
&NBSP;	
ISO9001	