

Inspection Report


Report No.: XYBA-141104
Supplier : XY-GLOBAL

Inspection Date: 7th Dec-, 2014
Inspector:LEO

Inspection only for: PO . XYBA-141104 Item No. XY21ZC023	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC023	6000pcs	7% inspection	0pcs	No failure	6000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

11

品名	铝合金CNC加工件CNC件
材料	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
规格	定制
数量	10000件
单位	件
重量	0.5kg
尺寸	100mm x 100mm x 10mm
公差	±0.01mm
表面处理	阳极氧化
包装	纸箱
交货期	10天
备注	

1. 1. CNC

2.

AL6061 AL6065 AL6063 AL7075

4. □□□□□□□□□□□□□□□□ □□□□

5.□□□□□□±0.01□□

6. 100

7.

8. 25-30

9. □□□□□□□□□□□□□□ □□□□□□□□□□□□

10.

11 □ □ □ □ □ □ □ □ ISO 9001

--	--	--	--	--

1.10 □□□□□ISO□□

2.

3. □□□□□□□□□□□□□□

4. □□□□□□□□

5.□□□□□

6.□□□□□□

7. □□□□□□□□□□

--	--	--	--	--

[illegible][illegible]

□□□□□□□□□□ ISO9001

[illegible]

OEM					
-----	--	--	--	--	--