

Inspection Report

Report No.: XYDN-140619

Inspection Date: 15th July, 2014

Supplier: XY-GLOBAL

Inspector: Leo

Inspection only for: PO . XYDN-140619 Item No.2530-400	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
2530-400	800PCS	1% inspection	0pcs	No failure	800pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product

[illegible]