

Inspection Report

Report No.: XYWD-140626
Supplier: XY-GLOBAL

Inspection Date: 20th July, 2014
Inspector: Leo

Inspection only for: PO: XYWD-140626 Item No. XY31SY43	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY43	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure, below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Customer: XY Electronics Technology Co., Ltd		Product Type: XY31SY43		Inspection Date: 2014.07.20	
Part No: XY31SY43		Lot No: XY31SY43		Inspector: Leo	
Quantity: 50000PCS		Inspection Quantity: 5000PCS		Pass Rate: 100%	
1. General Inspection: The product is in good condition, no defects found. 2. Dimensional Inspection: The product is in good condition, no defects found. 3. Surface Inspection: The product is in good condition, no defects found. 4. Assembly Inspection: The product is in good condition, no defects found. 5. Final Inspection: The product is in good condition, no defects found.					
Inspector: Leo Signature: _____ Date: 2014.07.20					

5. Product:

6. report

品名	汎用部品CNC加工品汎用部品CNC加工品
材質	材質 AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
仕様	仕様
数量	数量
単位	単位
公差	公差
表面処理	表面処理
検査	検査
納期	納期
保管場所	保管場所
梱包	梱包
備考	備考
1.汎用部品CNC加工品	
2.汎用部品CNC加工品	
汎用部品AL6061 AL6065AL6063AL7075	
4.汎用部品CNC加工品 仕様	
5.汎用部品±0.01mm	
6.汎用部品100mm	
7.汎用部品CNC加工品	
8.汎用部品25-30mm	
9.汎用部品CNC加工品 汎用部品CNC加工品	
10.汎用部品CNC加工品	
11汎用部品ISO 9001	
汎用部品	
1.10汎用部品ISO加工	
2.汎用部品CNC加工品	
3.汎用部品CNC加工品	
4.汎用部品CNC加工品	
5.汎用部品	
6.汎用部品	
7.汎用部品CNC加工品	
汎用部品	
汎用部品CNC加工品	
汎用部品CNC加工品	
汎用部品ISO9001	
汎用部品CNC加工品	
汎用OEM加工品	