

## Inspection Report

Report No.: XYSK-140603  
Supplier : XY-GLOBAL

Inspection Date: 2<sup>th</sup> July, 2014  
Inspector: Leo

|                                                                |                            |
|----------------------------------------------------------------|----------------------------|
| Inspection only for:<br>PO . XYSK-140603    Item No. XY31SY003 | Inspection Result:<br>PASS |
|----------------------------------------------------------------|----------------------------|

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY31SY003   | 6000PCS       | 1% inspection | 0pcs         | No failure          | 6000pcs         |

### Appearance Inspection :

No failure,

### Dimension Inspection:

No failure , below measurement report for reference.

### Assembly Test:

No failure

### Inspection Summary

The inspection sample plan is 100% inspection.

### Digital photo records :

|                                                                                     |                                                                                     |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|   |  |
| 1. Packing                                                                          | 2. Product                                                                          |
|  |  |
| 3. Product                                                                          | 4 Product                                                                           |
|  |  |
| 5. Product:                                                                         | 6. report                                                                           |

11

|    |                                                |
|----|------------------------------------------------|
| 品名 | 品名表示CNC加工品CNC加工品                               |
| 材質 | 材質 AL6061 AL6065AL6063AL7075SUS304SUS303SUS316 |
| 仕様 | 仕様                                             |
| 数量 | 数量                                             |
| 単位 | 単位                                             |
| 備考 | 備考                                             |
| 品名 | 品名表示CNC加工品CNC加工品                               |
| 材質 | 材質 AL6061 AL6065AL6063AL7075SUS304SUS303SUS316 |
| 仕様 | 仕様                                             |
| 数量 | 数量                                             |
| 単位 | 単位                                             |
| 備考 | 備考                                             |
| 品名 | 品名表示CNC加工品CNC加工品                               |
| 材質 | 材質 AL6061 AL6065AL6063AL7075SUS304SUS303SUS316 |
| 仕様 | 仕様                                             |
| 数量 | 数量                                             |
| 単位 | 単位                                             |
| 備考 | 備考                                             |
| 品名 | 品名表示CNC加工品CNC加工品                               |
| 材質 | 材質 AL6061 AL6065AL6063AL7075SUS304SUS303SUS316 |
| 仕様 | 仕様                                             |
| 数量 | 数量                                             |
| 単位 | 単位                                             |
| 備考 | 備考                                             |

1. 1. CNC

2.

AL6061 AL6065 AL6063 AL7075

4. □□□□□□□□□□□□□□□□ □□□□

5.□□□□□□±0.01□□

6.      100  

7.

8. 25-30

9. □□□□□□□□□□□□□□□□ □□□□□□□□□□□□□□

10.

11□□□□□□□□ISO 9001

[illegible]

1.10 100000 ISO 100

2. □□□□□□□□□□□□

**3.**

4.

5. □□□□□

6.□□□□□□

7. □□□□□□□□□□□□□□□□

|  |  |
|--|--|
|  |  |
|--|--|

[illegible][illegible]

□□□□□□□□□□ISO9001

[illegible]

|     |
|-----|
| OEM |
|-----|