

AL6061



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYK-130821
Supplier : XY-GLOBAL

Inspection Date: 23th Sep-, 2013
Inspector: LEO

Inspection only for: PO . XYK-130821 Item No.1300452	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1300452	500PCS	10% inspection	0pcs	No failure	500pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.


Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

物料名称	铝棒 CNC加工
规格	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316
长度	1000mm
重量	0.0000kg
材质	AL6061
表面处理	阳极氧化
公差	±0.01mm
数量	10000
交货期	10天
备注	1. Name: 铝棒 CNC加工
	2. Process: 阳极氧化
	3. Material: AL6061 AL6065AL6063AL7075
	4. Length: 1000mm
	5. Tolerance: ±0.01mm
	6. Quantity: 10000
	7. Specification: 阳极氧化
	8. Surface: 25-30um
	9. Accessoried: 阳极氧化
	10. Material: Austrial
	11. ISO 9001
	1. 10000 ISO
	2. 10000
	3. kinds available
	4. 10000
	5. 10000
	6. 10000
	7. 10000
	1. 10000
	2. 10000
	3. ISO9001
	4. 10000
	5. 10000