

Inspection Report

Report No.: XYSL-150613

Supplier : XY-GLOBAL

Inspection Date: 18th July, 2015

Inspector: Leo

Inspection only for:	<u>Inspection Result:</u>
PO . XYSL-150613 Item No. XY31XL011	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL011	8000PCS	1% inspection	Opes	No failure	8000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing

2. Product



3. Product

4 Product



5. Product:

6. report

[illegible]

Safety is our serious job for our worker and engineer team

