

Inspection Report

Report No.: XYDA-150304
Supplier : XY-GLOBAL

Inspection Date: 1st Apr, 2015
Inspector: Leo

Inspection only for: PO : XYDA-150304 Item No. XY31CY024	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY024	23000PCS	1% inspection	0pcs	No failure	23000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Product Name: XY31CY024
Product Type: XY31CY024
Inspection Date: 2015.04.01
Inspector: Leo

Inspection Result: PASS

Inspection Method: 100% inspection

Inspection Location: XY Electronics Technology Co., Ltd

Inspection Equipment: XY31CY024

Inspection Environment: XY31CY024

Inspection Results:

Item	Inspection Item	Inspection Result	Inspection Method	Inspection Equipment	Inspection Environment
1	Appearance	OK	Visual	XY31CY024	XY31CY024
2	Dimension	OK	Caliper	XY31CY024	XY31CY024
3	Assembly	OK	Assembly	XY31CY024	XY31CY024
4	Function	OK	Function	XY31CY024	XY31CY024
5	Material	OK	Material	XY31CY024	XY31CY024
6	Storage	OK	Storage	XY31CY024	XY31CY024
7	Transportation	OK	Transportation	XY31CY024	XY31CY024
8	Usage	OK	Usage	XY31CY024	XY31CY024
9	Maintenance	OK	Maintenance	XY31CY024	XY31CY024
10	Disposal	OK	Disposal	XY31CY024	XY31CY024

Inspection Summary: All inspection items passed.

Inspection Conclusion: The product is qualified for shipment.

Inspection Signatures: Leo

Inspection Date: 2015.04.01

5. Product:

6. report

[illegible]