

Inspection Report

Report No.: XYKB-140519

Inspection Date: 14th Jun, 2014

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO : XYKB-140519 Item No. XY72YM015	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM015	1000PCS	1% inspection	Opes	No failure	1000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	XY-GLOBAL 深圳市真朴电子科技有限公司 XY Electronics Technology Co., Ltd Inspection Report Report No.: XYKB-140519 Product Name: XY72YM015 Inspection Date: 14 Jun 2014 Inspector: Leo Inspection Result: PASS Inspection Method: 100% inspection Inspection Location: XY Electronics Technology Co., Ltd Inspection Equipment: XY72YM015 Inspection Environment: 25±2℃, 50%~80%RH Inspection Personnel: Leo Inspection Result: PASS Inspection Conclusion: The product meets the requirements of the inspection plan.
5. Product:	6. Dimensions report:

