

Inspection Report

Report No.: XYF-130819
Supplier : XY-GLOBAL

Inspection Date: 11th Sep, 2013
Inspector: LEO

Inspection only for: PO . XYF-130819 Item No. screw cap	<u>Inspection Result:</u> PASS
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
screw cap	8000Set	100% inspection	0pcs	No failure	8000Set

Appearance Inspection :

No failure.

Dimension Inspection:

No failure, below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :

[illegible]

6. inspection reports

[illegible]